







CIRCUIT BREAKER



PIMS




PLUGS



AIR OUTLET



GAZ EXHAUST



VACUUM



N2



N2 PURGE



AIR INTLET



WATER INTLET



WATER OUTLET

HATCHCO
CONCRETE

USE TR0203 FOR LOW DC PROCESS
1 Check Gas sensor / Check TC contact before starting
Do Not Exceed over 1000K

AOC 480-000-0401





=AXIC=

493 Gianni Street • Santa Clara, CA 95054
Tel: 408-980-0240 • Fax: 408-980-0524

www.axic.com
postmaster@axic.com



JETFIRST

CKT#5,7,9
FF PNL HN1B
CHASE#1



ON



OFF



ALARM



Do Not Power Down

TYPES

0c to 1000c

to 1000c

TR01

SILICON ONLY

0 SECOND MAX TIME DWELL

USE TR02/03 FOR LOW O₂ PROCESS
1. Check Gas panel Check TC contact before starting
Do Not Process over 1000c

TC1 INSTALLED

JETFIRST

ON

OFF


Do Not Power Down

ALARM











QUALIFLOW-JIPELEC 34 FRANCE

TYPE

TEST 200 A/C

REF

CN-040085-513 CE

VOLTS

3x400V+N+PE

KW

62

AMP

93

Hz

60

YEAR

2004